



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region III

841 Chestnut Building

Philadelphia, Pennsylvania 19107

RECORD OF SPCC INSPECTION

SPCC CASE NUMBER: WV-91-011 DATE 1-17-91
NAME: Pennzoil Company - Etowah ^{terminal} DATE FACILITY STARTED
ADDRESS: 1015 Barlow Drive OPERATIONS: 1933
CITY: Chambersburg STATE: WV
COUNTY: Mon PHONE: 304-342-8161

FACILITY OWNER/OPERATOR INFORMATION (IF DIFFERENT FROM ABOVE):

NAME: SAME
ADDRESS: _____
CITY: _____ STATE: _____
PHONE: _____

TYPE OF FACILITY: INDUSTRIAL _____, COMMERCIAL ☒, AGRICULTURAL _____,
PUBLIC _____, WELL DRILLING _____ OIL PRODUCTION _____,
STORAGE _____, WASTE TREATMENT _____
OIL STORAGE CAPACITY: ABOVEGROUND 4,000,000 GALLONS ☒
UNDERGROUND _____ GALLONS

SPCC PLAN REVIEW: PLAN PREPARED/AVAILABLE YES ☒ NO _____
PLAN CERTIFIED PER 112.3 YES ☒ NO _____
DATE CERTIFIED: 6-3-83
NAME OF ENGINEER: B. R. LAWRENCE
LICENSE NUMBER: 16398 STATE _____

DATE THE FACILITY FIRST REQUIRED PLAN: LA

RECORD OF SPCC PLAN REVIEW (EVERY 3 YEARS) AVAILABLE: YES ☒ NO _____
SPILL OF MORE THAN 1000 GALLONS IN PAST 12 MONTHS: YES ☒ NO ☒
IF YES, WAS PLAN SUBMITTED PER 112.4: YES _____ NO _____
TWO SPILLS, HARMFUL QUANTITIES, IN PAST 12 MONTHS: YES _____ NO ☒
IF YES, WAS PLAN SUBMITTED PER 112.4: YES _____ NO ☒
CLOSEST WATERWAY: ELK River DISTANCE: 75 Feet
ROUTE OF ENTRY: To west side of Facility

DURING THIS INSPECTION A COPY OF THE FACILITY'S SPCC PLAN WAS REQUESTED FOR REVIEW BY THE REGIONAL SPCC COORDINATOR. THE COPY OF THE SPCC PLAN WAS PROVIDED TO THE INSPECTORS (YES/NO). IF NOT, THE COPY WILL BE FORWARDED BY CERTIFIED MAIL, RETURN RECEIPT REQUESTED, WITHIN TEN (10) WORKING DAYS TO THE SPCC COORDINATOR.

I acknowledge that an SPCC Inspection of this facility was conducted on the 17 day of JAN, 19 91.

FACILITY REPRESENTATIVE SIGNATURE: Opus Sherrard

INSPECTORS SIGNATURES: Jerry Sasser

COPY OF THIS RECORD PROVIDED TO FACILITY OPERATOR (YES/NO) YES

SPCC CASE NO. WV-91-011
 DATE(S) OF INSPECTION: 1-17-91

MEMORANDUM

TO: VINCENT E. ZENONE, SPCC COORDINATOR, EPA REGION III

FROM: Jerry SWEENEY

SUBJECT: SPCC INSPECTION AT (FACILITY) Pennacoil
 (ADDRESS) 1015 Barlow Drive
 (CITY) Charleston
 (COUNTY) Marshall
 (STATE) WV

DATE OF FACILITY START OPERATIONS: 1933

GENERAL FACILITY INFORMATION:

TOPIC	FROM PLAN (YES/NO)	FROM INSPECTION
PLAN POSTED	<u>yes</u>	
NOTIFICATION PROCEDURE	<u>yes</u>	
SPILL EQUIPMENT	<u>yes</u>	
BERMS/DIKES	<u>yes</u>	<u>Concrete Block & Berch</u>
FACILITY DRAINAGE	<u>yes</u>	<u>Sepantou -</u>
BYPASS VALVES	<u>yes</u>	<u>To Sepantou from Tank</u>
LEVEL ALARMS ON TANKS	<u>No</u>	
INSPECTIONS/RECORDS	<u>yes</u>	<u>Records kept at office</u>
PERSONNEL TRAINING	<u>yes</u>	<u>Annual Training</u>
SECURITY	<u>yes</u>	<u>Warning - Lighting</u>

SPCC PLAN EMPHASIS (PREVENTION), (CONTROL), COUNTERMEASURES)

SPILL HISTORY:

SOURCE OF SPILL INFORMATION: FACILITY _____ STATE _____ RESPONSE CENTER ✓
 USCG _____ LIST ALL PAST SPILL EVENTS WHICH HAVE OCCURRED AT THIS FACILITY.

DATE	VOLUME	LOCATION	REPORTED
<u>Nov-1-89</u>		<u>@ Facility (One quart spill)</u>	<u>Y</u> <u>N</u>

SPCC CASE NO. WV-91-011
DATE(S) OF INSPECTION: 1-17-91**ABOVEGROUND STORAGE:**GIVE INFORMATION ON EACH ABOVEGROUND TANK AT THIS FACILITY. GROUP TANKS
BY INSTALLATIONS. INFORMATION NOTED BELOW REFLECTS TANK INSTALLATIONS ACTUALLY
INSPECTED THIS DATE.

TANK ID - CAPACITY (GAL/BBL) - PRODUCT - SECONDARY CONTAINMENT - OBSERVATION

All Tanks are properly DikeGood ConditionVery Cleanwell MAINTAINED**UNDERGROUND STORAGE:**GIVE INFORMATION ON EACH UNDERGROUND TANK AT THIS FACILITY.
INFORMATION NOTED BELOW REFLECTS TANK INSTALLATIONS ACTUALLY INSPECTED THIS DATE.

TANK ID - CAPACITY (GAL/BBL) - PRODUCT - SECONDARY CONTAINMENT - OBSERVATION

None**COMMENTS AND OBSERVATIONS:**

Company found to be in compliance. SPCC Plan recently updated.
Very Clean operation - with good security measures.
Capacity of Petroleum products. 4,200,000 gallons - Diking: Very
clean at time of inspection. Company personnel well
trained with the industry. Very cooperative to EPA
Inspector. Updated SPCC plan attached. All Tanks
valves are well maintained. Piping in good condition
& kept well painted. Separator functioning properly.
No visible sign of oil on ground on entering stream
way adjacent to facility. Loading & unloading areas very clean.

ORIGINAL
SPCC CASE NO. WYV-91-011
DATE(S) OF INSPECTION: 1-12-91

DIAGRAM

SEE ATTACHED PLAN.